

02. Cold drawing

The drawing process consists in reducing the lubricated wire rod through the die's, reducing its diameter and increasing its length. Fine wire is made by a multiple-block machine, because the reduction cannot be performed in a single step.

The wire drawing process is one of the industrial methods used to obtain small diameters, with narrow tolerances and accurate mechanical properties.