



Rehabilitación del hormigón

En colaboración con el estudio de Arquitectura de Alicante S+L, hemos publicado un manual sobre rehabilitación del hormigón afectado por corrosión en las armaduras en edificios de costa.

Los arquitectos Miguel Salvador Landmann y Antonio Salmerón Martínez dirigen el estudio de arquitectura S+L en Alicante y desde hace 15 años se especializan en la elaboración de dictámenes

de lesiones y proyectos de reparación, lo que les acredita como expertos en el sector.

El libro está disponible en español en:

www.cedinox.es

Publicaciones/Documentos on line

Rehabilitation of concrete

Thanks to S+L Architecture from Alicante, Spain, we have published this manual about the rehabilitation of the concrete affected by reinforcement corrosion in buildings by the beachfront.

Miguel Salvador Landmann and Antonio Salmerón Martínez, architects, have led S+L Study of Architecture in Alicante for more than 25 years. They specialize in the assessment of damage, analysis of risks and repair projects development.

The manual is only available in Spanish at www.cedinox.es


www.cedinox.es

Publications/Online documents



www.cedinox.es

RIESGOS DEL SISTEMA ACTUAL DE REPARACIÓN DEL HORMIGÓN ARMADO. NUEVOS PLANTEAMIENTOS CON ACERO CORRUGADO INOXIDABLE



Antonio SALMERÓN MARTÍNEZ
Miguel SALVADOR LANDMANN

Rebarino
Corrugado Acero Inoxidable